

S/053/0065  
cc: Lynn  
**RECEIVED**  
MAR 07 2011  
DIV. OF OIL, GAS & MINING

## UTAH 3809 COMPLIANCE INSPECTION REPORT

*Contract:* U-78598

*Field Office:* UTC030

*Operator(s):* Color Country Rock –Jeff Fawcett (435 674-2434)

*Project name:* Snow White Marble Quarry

*Location:* T39S R19W Sec 9 SWSE

*Disturbance:* Operator reclaimed the two open-cuts in contact metamorphosed Callville Limestone (marble) adjacent to the Mineral Mountain rhyolitic intrusion. The workings had consisted of two open-cuts with dumps that are about 100 ft by 75 ft and 150 ft by 50 ft in size. The NW site (0.68 acres) and the SE site (0.71 acres) both total 1.39 acres of disturbance. Lyle Jessop (Austin Jessop) was reclaiming the access roads.

*Hazardous Materials on Site:* None/The site is stable and fairly clean.

*Comments:* No activity in last 9 years.

*Instructions to Operator:* None.

*Recommended Action(s):* Notice expired must reclaim- \$15,000 bond held is acceptable-contact UDOGM.

*Photographs Taken:* See photographs below.

  
*Inspector:* Russell Schreiner

*Date of Inspection:* December 3, 2010

*Reviewed by:* \_\_\_\_\_

*Date:* \_\_\_\_\_

FM, St. George Field Office





View of the reclaimed northern open-cut and access road.





Overview of the reclaimed northern open-cut and access road.





Close-up view of the reclaimed southern access road and open-cut.





View of 322L CAT excavator used for the reclamation on the south access road.